

Dear Valued Business Partner,

MONITOUCH

**Notice of end of repair acceptance for
“V8**-U5** series (V8 series (HW Ver. a-d(e)) /UG40 series**

Thank you very much for your continued patronage of Fuji Programmable Operator Interface - MONITOUCH.

This is the notification that the repair of some models of V8 series/UG40 series will be terminated. Please review the following information.

1. Schedule of end of repair



[HMI]

Inch	V8 Model	UG Model	Hardware Version *1	Discontinued *2	End of Repair	Components which cannot be repaired
12.1	V812S-U5**	UG540H-VS1	"a" - "d"	September 2013	September 2020	Backlight *3
	V812SD-U5**	UG540H-VS4				
	V812iS-U5**	UG540H-VH1				
	V812iSD-U5**	UG540H-VH4				
	V812S series	UG540H-V series				
10.4	V810S-U5**	UG440H-VS1				
	V810SD-U5**	UG440H-VS4				
	V810iS-U5**	UG440H-VH1				
	V810iSD-U5**	UG440H-VH4				
	V810S series	UG440H-V series				
	V810T-U5**	UG440H-TS1				
	V810TD-U5**	UG440H-TS4				
	V810iT-U5**	UG440H-TH1				
	V810iTD-U5**	UG440H-TH4				
V810T series	UG440H-T series					
8.4	V808SD-U5**	UG340H-VS4	"a" - "e"			
	V808iSD-U5**	UG340H-VH4				
	V808S series	UG340H-V series				

*1 For model and hardware version, please refer to the label on the back of HMI.

*2 These products were manufactured in 2009 and before.

*3 V812-FL, spare parts of backlight, will also be discontinued.



Model

Hardware Ver.

[Peripheral devices]

Type	UG Model	Description	Discontinued	End of Repair
Peripheral devices	UG00A-VIS	Video input 4ch + Audio output for UG40/UG630	September 2013	September 2020
	UG00A-RIS	RGB input 1ch + Audio output for UG40/UG630		
	UG00A-ROS	RGB output 1ch + Audio output for UG40/UG63		
	UG00A-SUD	Audio output for UG40/UG630		
	UG00A-VRI	Video input 2ch + RGB input for UG40		
	UG00A-RI2	RGB input 2ch for UG40		
	UG03I-J	OPCN-1		
	UG03I-T	T-Link		
	UG03I-S	SX Bus		
	UG03I-P	PROFIBUS-DP		
	UG03I-D	DeviceNet		

Repair of other than those above models and hardware version is continuously acceptable.

The repair of above models will be terminated as mentioned in the table.

However, it is undeniable that the repair or maintenance would be impossible because of running out of component's stock or the supply disruption of the component by its manufacturers.

We would like to recommend you to promote the replacement to successor models.

David Schrader

David L. Schrader

General Manager

AC Drives and HMI Departments

Masayuki Max Fukumoto

Masayuki Max Fukumoto

International Sales and Product Specialist

HMI Department

Inquiry Type	Contact Name	Contact Phone	Contact Email	Purpose of Inquiry
Tech Support	Joe Lyons	(201) 490-3921	hmisupport@fujielectric-a.com	Technical support, Training, Product Application Support
Customer Service	HMI Customer Service	(510) 403-7863	x-fea-hmi-group@fujielectric.com	Product Price & Availability Order Processing/Shipment
General Inquiry	Masayuki Max Fukumoto	Direct: (201) 490-3927 Cell: (848) 256-6378	fukumoto-masayuki@fujielectric.com	General Inquiry