



HP Range	Inspection Fee
25-125 HP	\$500.00
150-450 HP	\$750.00
500-1000 HP	\$1,000.00

## Effective May 1st, 2024

- Inspection Fee includes complete handling and processing of the case (indirect labor is included as well as the direct labor to troubleshoot the product). An inspection fee is not charged for product failures determined to be under Warranty.
- Drives rated 20Hp and below will not be accepted for return and repair.
- Purchase orders to be received prior or at the same time of product being shipped back to Fuji Electric. No work will be proceed without a purchase order, product will be returned if a purchase is not received within 5 working days of the product arrival.